









installed on exterior doors: roof sun deck, dining room balcony, 5th floor north balcony, etc





installed on lobby reception desk, enclosed sun deck east exits, patient wing east toilets,





installed throughout enclosed sun deck floors and elsewhere







5

4

found installed only on patient wing maintenance stairwell balconies, 2nd floor and up








3

1 installed in 5th floor north corridor, junior physicians' houses 2 installed in 5th floor north

corridor

installed on main window assembly in reading room










installed in entryway of former staff housing (bunker)




not found installed



2





3

not found installed



